Notes o/ drawn with 18mm material. Quality plywood recommended. With adequate driver-to-driver bracing one could get away with as little as 12mm. 1/ for 2 x Mark Audi but recommended. Braces should run in the direction of the line 5/ beveling front vertical edges recommended 6/ stabilizing plinth recommended 7/ designed to be used as a quadrupole with the inverted upper box in front -rear firing mode so the drivers are near ear height. Lower box can have drivers firing to the side or front-back.

798 [31 13/32]

> 762 [30]

> > 114 [4 1/2]

> > > 178 [7]

214

[8 7/16]

[8 13/32]

